CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242428

Address: 3116 SW SUMMIT VIEW TRL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Wednesday, March 12,

Residential 2025

Corrective Action Required:

1 Miscellaneous Not inspected

Correction -Exterior garage portal sheeting needs to extend to both top plates to tie in

Corrective Action Required:

2 Misc

-purlin and purlin supports not to plans (see south half of home, see above

bed 2)

-fire block wall space to ceiling space at all furr downs in basement where

missing(see rec room)

-missing stud packs each side of basement slider

-all "B" columns to be of correct size

Comments: