

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20245069  
Address: 2615 SW FIREFLY LN, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mitchell Schwarz	Failed	Thursday, March 27, 2025

Corrective Action Required:

1	Misc	-provide weld certificate for beam welds -furr down in garage when unable to properly install r19 insulation -smoke in bed 3 to be more than 3' from bathroom -protect dryer vent at top plate -header at master suite entry not to plans -seal top plate penetration N master suite wall -move or protect wiring at attic access -seal top plate penetrations at master suite toilet room -roof supports landing on non load bearing wall, not to plans see master/bed 3. Check throughout -uncover covered roof framing at rear patio
---	------	--

Comments: