

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20222088

Address: 1305 SE WINDBREAK DR, LEES SUMMIT, MO 640811309 SE WINDBREAK DR, LEES SUMMIT, MO 640811313 SE WINDBREAK DR, LEES SUMMIT, MO 640811317 SE WINDBREAK DR, LEES SUMMIT, MO 640811321 SE WINDBREAK DR, LEES SUMMIT, MO 640811325 SE WINDBREAK DR, LEES SUMMIT, MO 640811329 SE WINDBREAK DR, LEES SUMMIT, MO 640811331 SE WINDBREAK DR, LEES SUMMIT, MO 640811335 SE WINDBREAK DR, LEES SUMMIT, MO 640811424 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811428 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811432 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811433 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811429 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811425 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811421 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811417 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811413 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811409 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811405 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811344 SE WINDBREAK DR, LEES SUMMIT, MO 640811340 SE WINDBREAK DR, LEES SUMMIT, MO 640811336 SE WINDBREAK DR, LEES SUMMIT, MO 640811332 SE WINDBREAK DR, LEES SUMMIT, MO 640811328 SE WINDBREAK DR, LEES SUMMIT, MO 640811324 SE WINDBREAK DR, LEES SUMMIT, MO 640811320 SE WINDBREAK DR, LEES SUMMIT, MO 640811316 SE WINDBREAK DR, LEES SUMMIT, MO 640811312 SE WINDBREAK DR, LEES SUMMIT, MO 640811308 SE WINDBREAK DR, LEES SUMMIT, MO 640811304 SE WINDBREAK DR, LEES SUMMIT, MO 640811377 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811373 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811369 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811320 SE VANTAGE POINT DR, LEES SUMMIT, MO 640811365 SE VANTAGE POINT DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection	Bobby Richest	Failed	Tuesday, April 29, 2025

Informational:

1

Misc

1-26-25 BR Erosion control is up and working order.

2-4-25 BR Erosion control is up and working order.

2-20-25 BR Erosion control is up and working order.

3-4-25 BR Erosion control is up and working order.

4-29-25 RH. Silt socks full and need replaced or cleaned out. No Silt fence along curbs. Mud over curbs needs cleaned. This need cleaned up immediately. Seeding will also be needed.

Comments: