

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20245321, Public Works Right of Way Permit
Address: 5050 NE LAKEWOOD WAY, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Eric Wiggins	Partial	Thursday, May 08, 2025

Corrective Action Required

1	Misc	Site visit. I was out today 12-17-24 to do the inspection. Rodriguez underground was out working along Lakewood Way, heading north. As of today their insurance is incomplete and they are not allowed to be working until this is resolved. I did ask them to stop working until we have the correct insurance policy. This is required by the City of Lee's Summit law department. I will continue to monitor this site.
---	------	--

Corrective Action Required

2	Misc	Site visit. No workers present. I will continue to monitor.
---	------	---

Corrective Action Required

3	Misc	Site visit. No workers present.
---	------	---------------------------------

Corrective Action Required

4	Misc	Site visit. No workers present. Pits are fenced off. I will continue to monitor.
---	------	--

Corrective Action Required

5	Misc	Site visit. Workers were on site at Todd George Rd and Strother. They are off the road and the site is clean.
---	------	---

Corrective Action Required

6	Misc	Site visit. Work has continued. They are remaining off the road way. I will continue to monitor.
---	------	--

Corrective Action Required

7	Misc	Site visit. Rodriguez underground was out working today, they still do not have all the insurance that is required to do work in the ROW. I have asked them to stop work until all insurance is received. I emailed Geoff at K&W to let them know that work has stopped. I have also had to tell Rodriguez twice to make sure they have signs on their trucks.
---	------	--

Corrective Action Required

8	Misc	No workers present, Restoration has been started at a few
---	------	---

spots of this job. I only saw 1 open pit and it was fenced off. I will continue to monitor.

Comments: