

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRSUBD20236023

Address: 3201 NE WILSHIRE DR, LEES SUMMIT, MO 64064551 NE MEADOWVIEW DR, LEES SUMMIT, MO  
640643200 NE WILSHIRE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control Inspection</b>	Nick Scott	Partial	Thursday, April 24, 2025

### Corrective Action Required:

1	Misc	Retirement home 10-14-24 NS Gutter buddies need to be installed around construction site 10-31-24 NS Site Visited and no work has been done since last inspection 11-6-24 NS Site Visited and still no erosion control issues 11-13-24 NS Site Visited and still no erosion control issues 12-13-24 NS Site Visited and still no erosion control issues 12-31-24 NS Site Visited and still no erosion control issues 1-10-25 NS Site Visited and still no erosion control issues 1-16-25 NS Site Visited and still no erosion control issues 1-24-25 NS Site Visited and still no erosion control issues 1-31-25 NS Site Visited and still no erosion control issues 2-3-25 NS Site Visited and still no erosion control issues 2-10-25 NS Site Visited and still no erosion control issues 2-17-25 NS Site Visited and still no erosion control issues 2-24-25 NS Site Visited and still no erosion control issues 2-28-25 NS Site visited and it appears that no erosion control issues 3-6-25 NS Site visited and it appears that no erosion control issues 3-19-25 NS Site visited and saw fence down and the company went out while I was there. 4-3-25 NS Site visited and drove around jobsite and it appears that site does
---	------	---

not have a problem.

4-16-25 NS Site visited and it appears concrete spilled and the crew is cleaning it up.

4-24-25 NS Site visited and it appears that jobsite has no problems

**Comments:**