

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20226232
Address: 120 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Robb Popp	Partial	Thursday, May 15, 2025

Corrective Action Required:

1 FIRST FLOOR

**OK to top out one side for mechanical as neccessary
**OK to top out both sides at corridor1E-100H and 1E-100G for MEPs

*Existing side:

1E-314, 315B, 315C, 1E202A-1E-202H, 1E-203-1E207, 1E-220-1E-226, 1E-100k,
1E-149 through 1E-151a, 1E202-1E206, 2E-238 through 2E-242, 2E-420 through
2E-423, Corridor02-1E200A, 1E227, 1E-228, OR 7 1E-229, 1E280, 1E-231,
1E-218A, 1E-218B, 1E-216A, 1E-216B, 1E-172, 1E-173, 1E-174, 1E-175., Pre/Post
Bays 1E161-1E-157, 1E-181-1E-178, TLT 1E-164, 1E-213, 1E-214, 1E-216, 1E-310

**Addition side
-In wall complete

Corrective Action Required:

2 SECOND FLOOR

**OK to top out corridors for MEPs as neccessary

*EXISTING SIDE;

-2E419 electrical room ok to 1 side
2E-232, 2E-231B, 2E-234, 2E-235, 2E-237, 2E-236, 2E-112, 2E-121, 2E403, 2E410,
2E-241, 2E-412, 2E-409, corridor 2E-122, Office 2E-338, 2E-339, Exam 2E-331,
2E-332, 2E-337, 2E-336

2E-332, 2E-333, 2E-336, 2E-335, 2E-340, 2E-341, 2E-342, 2E-345, 2E-344,
2E-343-OK to 1 side

**ADDITION SIDE
-COMPLETE

Corrective Action Required:

3 THIRD FLOOR

**Addition side:

*Ok to top out for MEPs throughout

3E-104, 3E-209A, 3E-209B, 3E-211

3E-311 to 3E-323, 3E-326, 3E-335, 3E-350 to 3E-369, 3E-252 to 3E-255, 3E-257 to
3E-261, 3E-214-230, 3E-302-308, 3E-103, 3E-233, 3E-232, 3E-250'

-South exterior framing ok cover

-Elevator infill walls

-North stairwell walls ok

Comments: