CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245640

Address: 4420 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Erosion Control Inspection Residential		Jamie Simerly	Failed	Friday, May 16, 2025	
Corrective Action Required:					
1	DCM1 ESC	EROSION CONTROL REQUI	N CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE MED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
	REQUIRED NO	PERFORMED UNTIL EROSIG			
	FURTHER INSP				
		- Clean gravel out of street			
		- Remove portable toilet i	from street		
Corrective Action Required:					
2	DCM3 ESC	05-16-25 Jamie S, Erosion control needs to be reestablished at the front of			
	REQUIRED 2 DAY	the property.			
	4	• • •	IRED. EROSION CONTROLSI AYS.	HALL BE IN COMPLIANCE	

Comments: