CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Miscellaneous Inspection		Robb Popp	Partial	Friday, May 16, 2025	
Corrective Action Required:					
1	Misc	4F pre final			
		-Submit final third party inspection reports			
		-Install smoke seals at corridor doors			
		3F			
		-Install smoke seals at corridor, mechanical and stairwell		well	
		-EM light outside of 2345 not working			
		2349-Seal mechanical room ceiling			
		2348-Exterior GFCI faulty, check kitchen circuit (lights tied to multiple			
		breakers)			
		Mechanical room-Seal all penetrations			
		2342-Seal exterior penetration			
		2341-Exterior GFCI hot and ground reversed			
	2F				
		2248-GFCI at washing mac	hine not working		
		2242-Loose receptacle right of range			
		-Close opening in ceiling b	Close opening in ceiling box at stairwell		
		1F			
		G52-CO detector not funct	tioning		
		G58-Seal penetration			

Comments: