CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20250475 Address: 1917 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control Inspection Residential		Wes Bears	Failed	Tuesday, May 27, 2025
Corrective	Action Required:			
1	DCM1 ESC	EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
	REQUIRED NO			
	FURTHER INSP			
		-SPREAD GRAVEL FILTER		
Corrective	Action Required:			
2	DCM3 ESC	EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE		
	REQUIRED 2 DAY	WITHIN TWO BUSINESS DAYS.		
		Erosion control non existent left of gravel drive at front of lot.		
Corrective	Action Required:			
3	DCM1 ESC	EROSION CONTROL REQUI	RED. NO FURTHER INSPECT	IONS WILL BE
	REQUIRED NO FURTHER INSP	PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		

Comments: