CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #:PRRES20250365Address:2123 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Residential		Robb Popp	Not Ready	Wednesday, June 25, 2025	
Correct	ive Action Required:				
1	Misc	6/25/25 Inspection for "Need inspection on garage door portal framing, front			
		porch ceiling and back deck ceiling only"			
		-PFH nailed through moisture barrier- seal penetrations			
		-Front porch ceiling- already covered			
		-Back deck ceiling- Not framed at all			
			-CSPF at back- missing nailing pattern and full length king studs in corner		
		***Not ready			

Comments: