

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20202008, Public Infrastructure

Address: 2062 NW OBRIEN RD, LEES SUMMIT, MO 640812066 NW OBRIEN RD, LEES SUMMIT, MO 640812070 NW OBRIEN RD, LEES SUMMIT, MO 640812074 NW OBRIEN RD, LEES SUMMIT, MO 640812078 NW OBRIEN RD, LEES SUMMIT, MO 640812082 NW OBRIEN RD, LEES SUMMIT, MO 640812086 NW OBRIEN RD, LEES SUMMIT, MO 640812090 NW OBRIEN RD, LEES SUMMIT, MO 640812094 NW OBRIEN RD, LEES SUMMIT, MO 640812098 NW OBRIEN RD, LEES SUMMIT, MO 64081361 NW PATCH CT, LEES SUMMIT, MO 64081365 NW PATCH CT, LEES SUMMIT, MO 64081369 NW PATCH CT, LEES SUMMIT, MO 64081373 NW PATCH CT, LEES SUMMIT, MO 64081377 NW PATCH CT, LEES SUMMIT, MO 64081374 NW PATCH CT, LEES SUMMIT, MO 64081370 NW PATCH CT, LEES SUMMIT, MO 64081366 NW PATCH CT, LEES SUMMIT, MO 64081362 NW PATCH CT, LEES SUMMIT, MO 640812116 NW OBRIEN RD, LEES SUMMIT, MO 640812125 NW OBRIEN RD, LEES SUMMIT, MO 640812121 NW OBRIEN RD, LEES SUMMIT, MO 640812117 NW OBRIEN RD, LEES SUMMIT, MO 640812113 NW OBRIEN RD, LEES SUMMIT, MO 640812109 NW OBRIEN RD, LEES SUMMIT, MO 640812105 NW OBRIEN RD, LEES SUMMIT, MO 640812095 NW OBRIEN RD, LEES SUMMIT, MO 640812091 NW OBRIEN RD, LEES SUMMIT, MO 640812087 NW OBRIEN RD, LEES SUMMIT, MO 640812083 NW OBRIEN RD, LEES SUMMIT, MO 640812079 NW OBRIEN RD, LEES SUMMIT, MO 640812075 NW OBRIEN RD, LEES SUMMIT, MO 640812071 NW OBRIEN RD, LEES SUMMIT, MO 640812067 NW OBRIEN RD, LEES SUMMIT, MO 640812063 NW OBRIEN RD, LEES SUMMIT, MO 640812059 NW OBRIEN RD, LEES SUMMIT, MO 640812055 NW OBRIEN RD, LEES SUMMIT, MO 640812206 NW KILLARNEY LN, LEES SUMMIT, MO 640812210 NW KILLARNEY LN, LEES SUMMIT, MO 640812214 NW KILLARNEY LN, LEES SUMMIT, MO 640812218 NW KILLARNEY LN, LEES SUMMIT, MO 640812226 NW KILLARNEY LN, LEES SUMMIT, MO 640812230 NW KILLARNEY LN, LEES SUMMIT, MO 640812234 NW KILLARNEY LN, LEES SUMMIT, MO 640812238 NW KILLARNEY LN, LEES SUMMIT, MO 640812233 NW KILLARNEY LN, LEES SUMMIT, MO 640812229 NW KILLARNEY LN, LEES SUMMIT, MO 640812225 NW KILLARNEY LN, LEES SUMMIT, MO 640812221 NW KILLARNEY LN, LEES SUMMIT, MO 640812217 NW KILLARNEY LN, LEES SUMMIT, MO 640812213 NW KILLARNEY LN, LEES SUMMIT, MO 640812241 NW KILLARNEY LN, LEES SUMMIT, MO 640812100 NW OBRIEN RD, LEES SUMMIT, MO 640812222 NW KILLARNEY LN, LEES SUMMIT, MO 640812237 NW SUMMERFIELD DR, LEES SUMMIT, MO 640812058 NW OBRIEN RD, LEES SUMMIT, MO 640812120 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Bob Burns	Passed	Thursday, June 26, 2025

Corrective Action Required

1	Misc	Bond Inspection - The two pavement areas have been patched under the direction of Development Services Inspectors.
---	------	--

Closing. No other issues at this time.

Comments: