

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20250835
Address: 4001 SW MONDAVI LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Wes Bears	Failed	Wednesday, July 02, 2025

Corrective Action Required:

1	Miscellaneous Correction	4001 -missing stud in stud pack in garage -fire block the cut out at the dryer vent and the LVL cut out
---	--------------------------	---

Comments: