

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245803
Address: 2805 SW HEARTHSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection Residential	Dustin Agcopra	Partial	Monday, July 07, 2025

Corrective Action Required:

1	Misc	Repair downed silt fence
---	------	--------------------------

Corrective Action Required:

2	DCM3 ESC REQUIRED 2 DAY	07/01/25 Jamie S, Erosion control needs to be reestablished in front of property, street and sidewalk needed to be cleaned up. EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE WITHIN TWO BUSINESS DAYS. 7-7-26 Dustin A, sw has been cleaned and esc has been re-established. Esc must be maintained throughout project.
---	----------------------------	--

Comments: