

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20211958, Public Infrastructure

Address: 2107 SW HOOK FARM DR, LEES SUMMIT, MO 640822111 SW HOOK FARM DR, LEES SUMMIT, MO

640822115 SW HOOK FARM DR, LEES SUMMIT, MO 640822119 SW HOOK FARM DR, LEES SUMMIT, MO
640822123 SW HOOK FARM DR, LEES SUMMIT, MO 640822127 SW HOOK FARM DR, LEES SUMMIT, MO
640822131 SW HOOK FARM DR, LEES SUMMIT, MO 640822135 SW HOOK FARM DR, LEES SUMMIT, MO
640822139 SW HOOK FARM DR, LEES SUMMIT, MO 640822143 SW HOOK FARM DR, LEES SUMMIT, MO
640822147 SW HOOK FARM DR, LEES SUMMIT, MO 640822203 SW HOOK FARM DR, LEES SUMMIT, MO
640822207 SW HOOK FARM DR, LEES SUMMIT, MO 640822211 SW HOOK FARM DR, LEES SUMMIT, MO
640822215 SW HOOK FARM DR, LEES SUMMIT, MO 640822219 SW HOOK FARM DR, LEES SUMMIT, MO
640822210 SW HOOK FARM DR, LEES SUMMIT, MO 640822206 SW HOOK FARM DR, LEES SUMMIT, MO
640822202 SW HOOK FARM DR, LEES SUMMIT, MO 640822630 SW TRACKER LN, LEES SUMMIT, MO
640822626 SW TRACKER LN, LEES SUMMIT, MO 640822622 SW TRACKER LN, LEES SUMMIT, MO
640822618 SW TRACKER LN, LEES SUMMIT, MO 640822614 SW TRACKER LN, LEES SUMMIT, MO
640822610 SW TRACKER LN, LEES SUMMIT, MO 640822602 SW TRACKER LN, LEES SUMMIT, MO
640822506 SW TRACKER LN, LEES SUMMIT, MO 640822502 SW TRACKER LN, LEES SUMMIT, MO
640822503 SW TRACKER LN, LEES SUMMIT, MO 640822144 SW WHEATFIELD DR, LEES SUMMIT, MO
640822137 SW WHEATFIELD DR, LEES SUMMIT, MO 640822607 SW TRACKER LN, LEES SUMMIT, MO
640822611 SW TRACKER LN, LEES SUMMIT, MO 640822615 SW TRACKER LN, LEES SUMMIT, MO
640822619 SW TRACKER LN, LEES SUMMIT, MO 640822623 SW TRACKER LN, LEES SUMMIT, MO
640822627 SW TRACKER LN, LEES SUMMIT, MO 640822631 SW TRACKER LN, LEES SUMMIT, MO
640822635 SW TRACKER LN, LEES SUMMIT, MO 640822630 SW FIREFLY LN, LEES SUMMIT, MO
640822626 SW FIREFLY LN, LEES SUMMIT, MO 640822622 SW FIREFLY LN, LEES SUMMIT, MO
640822618 SW FIREFLY LN, LEES SUMMIT, MO 640822614 SW FIREFLY LN, LEES SUMMIT, MO
640822610 SW FIREFLY LN, LEES SUMMIT, MO 640822606 SW FIREFLY LN, LEES SUMMIT, MO
640822133 SW WHEATFIELD DR, LEES SUMMIT, MO 640822136 SW WHEATFIELD DR, LEES SUMMIT,
MO 640822132 SW WHEATFIELD DR, LEES SUMMIT, MO 640822128 SW WHEATFIELD DR, LEES
SUMMIT, MO 640822124 SW WHEATFIELD DR, LEES SUMMIT, MO 640822120 SW WHEATFIELD DR,
LEES SUMMIT, MO 640822116 SW WHEATFIELD DR, LEES SUMMIT, MO 640822112 SW WHEATFIELD
DR, LEES SUMMIT, MO 640822108 SW WHEATFIELD DR, LEES SUMMIT, MO 640822103 SW
WHEATFIELD DR, LEES SUMMIT, MO 640822107 SW WHEATFIELD DR, LEES SUMMIT, MO 640822111
SW WHEATFIELD DR, LEES SUMMIT, MO 640822121 SW WHEATFIELD DR, LEES SUMMIT, MO
640822125 SW WHEATFIELD DR, LEES SUMMIT, MO 640822129 SW WHEATFIELD DR, LEES SUMMIT,
MO 640822603 SW FIREFLY LN, LEES SUMMIT, MO 640822607 SW FIREFLY LN, LEES SUMMIT, MO
640822611 SW FIREFLY LN, LEES SUMMIT, MO 640822615 SW FIREFLY LN, LEES SUMMIT, MO
640822619 SW FIREFLY LN, LEES SUMMIT, MO 640822623 SW FIREFLY LN, LEES SUMMIT, MO
640822116 SW HOOK FARM DR, LEES SUMMIT, MO 640822618 SW BARLEY FIELD DR, LEES SUMMIT,
MO 640822614 SW BARLEY FIELD DR, LEES SUMMIT, MO 640822610 SW BARLEY FIELD DR, LEES
SUMMIT, MO 640822606 SW BARLEY FIELD DR, LEES SUMMIT, MO 640822607 SW BARLEY FIELD DR,
LEES SUMMIT, MO 640822611 SW BARLEY FIELD DR, LEES SUMMIT, MO 640822615 SW BARLEY FIELD
DR, LEES SUMMIT, MO 640822619 SW BARLEY FIELD DR, LEES SUMMIT, MO 640822110 SW HOOK
FARM DR, LEES SUMMIT, MO 640822140 SW WHEATFIELD DR, LEES SUMMIT, MO 640822606 SW

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Bob Burns	Partial	Wednesday, July 09, 2025

Corrective Action Required

1	Misc	Bond Inspection - Sanitary sewer manhole 50-325 closest to 2502 SW Tracker Ln. the pavement has settled around the manhole. This will need to be properly repaired.
---	------	---

Comments: