## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## OnlinePortal at DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20246296

Address: 2531 NE WOODLAND OAK CIR, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, July 09,

Residential 2025

Corrective Action Required:

1 Misc -I beam ledger through bolt not fully installed. Have engineer address ledger

support attachment to I beam not per detail 4/S3.1

-Engineer address support of the roof beam point load not centered to I beam.

Also, Plan calls for 1/4" steel web stiffener under the point load

\*\*OK TO INSULATE

**Comments:**