

June 5, 2018

Corey Walker
M-III Longview, LLC
4220 Shawnee Mission Parkway, Ste. 200B
Fairway, KS 66205

Re: Site Visit – June 4th, 2017
Old Longview Lake Dam and Spillway
Lee's Summit, MO
Olsson Project No. 017-0305

As requested, Olsson Associates (**Olsson**) visited the project site on Monday June 4th, 2018 to observe the existing condition of the Old Longview Lake Dam and Spillway. We observed construction safety fencing on both the east and west sides of the dam as shown in the photograph below.



In addition, we observed a syphon pipe set up to draw down the lake. The pipe was around 3 to 5 feet below the water surface. The pipe extended over the dam and extended near the toe of the slope of the dam. The syphon pipe is shown in the following photographs.



A small amount of water was still flowing through the eroded area on the west side of the dam. Visually, the dam, spillway and erosion channel do not appear to have changed since our previous visit. We have included a photograph of the erosion below.



We appreciate the opportunity to be of service to you on this project. This letter has been prepared for the exclusive use of Platform Ventures for specific application to the project discussed and has been prepared in accordance with generally accepted geotechnical engineering practices. No warranties, express or implied, are intended or made. If you have any questions regarding this letter, please contact us.

Sincerely,
Olsson Associates



Ian Dillon, PE



James Landrum, PE