

## 1000 West Nifong Boulevard, Building 1 Columbia, Missouri 65203 (573) 447-0292

September 24, 2019

Jennifer Thompson, Planner Development Services City of Lee's Summit, Missouri 220 SE Green Street Lee's Summit, MO 64063

## Re: Response to the City of Lee's Summit, MO Review for Application Number PL2019280-South M-291 Safety Storage, Plat 4A

- The scale is not scaling properly. Revised
- 2. Revise the Plat title Lot label to 4A rather than 2AB. Revise on the lot as well. Revised
- 3. When resubmitting, remove the former lot lines. Revised
- 4. Indicate the area for the lot in square footage as well as in acres. Revised
- 5. Revise the "approved" dedication paragraph to name the correct plat, please revise the plat to the requested lot # as requested by staff. Revised
- 6. Provide a note indicating the location of any oil and/or gas wells, if any, based on available information. Provide the source for this determination. Revised
- 7. Reference SW Raintree Dr. and the appropriate ROW width. Revised
- 8. Label the 5-foot sidewalk along SW Raintree Dr. Revised
- 9. The front building line doesn't seem to be reflected accurately (besides not scaling properly). It is correct

Is the 50' rear building line and 20' side building line accurate? Revised the 50' rear building line

10. The previous plat indicated a 15' sanitary sewer easement along the front p/l. Please reference this. It was there on the submitted plat, but there was no notation. Revised

- 11. Show and reflect accurately the Little Blue Force Main sewer easement that cuts through the property. Inquired and found condemnation case number. Added to the sewer notation. Sewer is accurately plotted.
- 12. How were the access easements previously dedicated? It appears they were dedicated by previous plats. The access easements are no longer needed and one of them will be under a building. Additional discussion is needed to determine best way to remove the easements (i.e quit claim deed or vacation of easement?). Easements were dedicated by plat. A vacation request is in place at the city.
- 13. Three 10' utility easements are not shown on this plat (please reference plat of record). Staff is aware there is a vacation of UE application going through the process. Please note the currently existing easements and once vacated, note the document #that vacated the easements. Revised
- Label the address of the lot. Revised
- 15. Are any new easements being dedicated as part of this plat? If so, the necessary easement language is needed for the plat. It is my understanding there will be no new easements.
- 16. Revise the plat dedication (and all other necessary locations), to reflect the revised plat title (lot #).

  Revised
- 17. Reference the location and limits of the 1% Annual Chance Flood, as set forth on the current FEMA maps, with reference to the panel number. Revised

Sincerely,

Crockett Engineering Consultants, LLC

David W. Borden, PLS 2002000244