

RELEASED FOR  
CONSTRUCTION  
As Noted on Plans Review

Development Services Department  
Lee's Summit, Missouri

11/04/2021



Install "Shoulder Ends" W8-25  
w/ W16-2aP (200') Sign  
200 feet North of Culvert

HEADWALL  
17238  
1008.81

HEADWALL  
17239  
1008.75

HEADWALL  
17240  
1008.92

HEADWALL  
17241  
1008.92

Slope  
3.66 to 1



32' North

52' South

17024  
1010.49  
EOA

17022  
1010.41  
EOA

HEADWALL  
17236  
1007.46  
HEADWALL  
17237  
1007.43

HEADWALL  
17234  
1007.56  
HEADWALL  
17235  
1007.59

No Road Improvements  
are being completed  
on the East side of Pryor Rd

17019  
1010.96  
EOA

Edge of Asphalt  
FG=1010.84'

Edge of Asphalt  
FG=1010.84'

Edge of Asphalt  
FG=1010.99'

Edge of Asphalt  
FG=1010.94'

Install OM2-1V Signs (8 Total)  
-Westside North end of Shoulder  
-Westside South end of Shoulder  
-Westside at north edge of culvert  
-Westside at south edge of culvert  
-Eastside North end of Shoulder  
-Eastside South end of Shoulder  
-Eastside at north edge of culvert  
-Eastside at south edge of culvert

17002  
1011.59  
EOA

17033  
1011.74  
EOA



Install "Road Narrow Sign" W8-25  
w/ W16-2aP (200') Sign  
200 feet South of Culvert

Survey Exhibit

DATE: 8-6-2021  
PROJECT NUMBER:  
Pryor Road

REV. TO DWG.:  
Pryor Road

SCALE:  
1" = 10'

North Culvert

SHEET 1 OF 1

Survey Exhibit

**North Culvert - Pryor Rd**

Pryor Road  
Lee's Summit, Jackson County, Missouri

**ENGINEERING**  
ENGINEERING & SURVEYING  
**SOLUTIONS**

50 SE 30TH STREET  
LEE'S SUMMIT, MO 64082  
P:(816) 623-9888 F:(816) 623-9849