

December 20, 2022

City of Lee's Summit, Missouri Attn: Gene Williams 220 SE Green Street Lee's Summit, MO 64063

RE: Woodside Ridge 2nd Plat (PL2020125)

We are responding to your comments dated November 4, 2022, and are submitting with this letter revised plans, and other required documents. Please find the original comments below; our responses are below in bold italics.

If you have any questions or need additional information, please do not hesitate to contact us.

Thanks,

Lete Selles

Julie Sellers, P.E.

Street and Stormwater Record Drawing Review

Sheet C121: It does not appear there is sufficient freeboard between the 100 year clogged/zero available storage and the top of dam. The Design and Construction Manual requires a minimum of 1.0 feet of freeboard between the top of dam and the 100 year WSE clogged. This may require: 1) a waiver if it can be justified, or 2) regrading or other modification to the detention basin.

A waiver has been submitted for the detention basin.

- 2. Sheet C122: The same issue appears evident for the detention basin within Tract J. *A waiver has been submitted for the detention basin.*
- 3. Master Drainage Plan: Please separate-out the Master Drainage Plan from the overall plan set for permitting and plot plan review purposes. *The Master Drainage Plan has been separated out for plot plan review.*
- Sheet C120: It appears the flowlines do not make sense at curb inlet 7-4. F/L in is shown at 957.76, and F/L out is shown at 958.48. Please reconcile. *The flowline has been revised and slopes updated.*