

LOGAN & ASSOCIATES, INC.
SOIL INSPECTION REPORT

NOT TO BE USED WITH SUBMITTALS – FOR BUILDERS INFORMATION ONLY

Subdivision: Goppert Acres

Lot #: 1F

Address: 713 SW 15th Cir

Builder: SAB Homes

City or County: Lee's Summit

Permit No.: PRRES2025-2578

SOIL CONDITIONS

☒ Original clay soil SOLID RED CLAY

() Soft clay soil _____

() Moist clay soil _____

() Unsuitable soil _____

() Rock _____

() Broken rock _____

() Waste Rock _____

() Tree roots _____

() Building debris _____

☒ Compacted Fill SOME

() Other _____

FOOTING RECOMMENDATION

☒ 16 x 8 w/2

() 16 x 8 w/4

() 16 x 12 w/4

() 24 x 8 w/5

() 24 x 12 w/5

() 30 x 8 w/6

() 30 x 12 w/6

() 36 x 8 w/6

() 36 x 12 w/6

() Other _____

COMMENTS: _____

Charles R. Logan, PE
Charles R. Logan, PE

Date: 7-11-25

