

Stormwater Pollution Prevention Plan Inspection Report

Project Name and Location: Blackwell

					
Weather: 91					
		∐Clo	oudy $oxtimes$ Sunny $oxtimes$ Rain $oxtimes$ Snowing/ Snow cover		
Date of inspection: 7/28/25	•	•			
Inspectors Name: Jessica Ekster					
Type of Inspection: $oxtimes$ Regular $oxtimes$ Rain event $oxtimes$ Other:					
Rain in last 24 hrs (inches): NA					
Owner/Permittee: Griffin Riley					
Current Site Condition: Active					
			-		
BMP Checklist	<u>Yes</u>	<u>No</u>	Current Construction/Active Areas:		
Inlet Barriers	\boxtimes		Vertical		
Sediment Barriers	\boxtimes				
Construction Entrance	\boxtimes				
Stream Crossings		\boxtimes			
Seed/Sod/Hydroseed/Mulch/Blanket		\boxtimes			
Sediment Basins & Discharge Locations		<u>N</u>			
Borrow Areas		\boxtimes			
General Site Conditions		<u>N</u>			
Concrete Washout	\boxtimes				

<u>Problem Areas/Special Observations (Note problem areas ONLY below):</u>

ВМР	Location	Observation, Effectiveness, & Corrective Actions Ordered
Stabilize	In-active	Stabilize all areas that have been inactive for 14+ days- Weeds are not
		considered vegetation.
Stabilize	Swale	Stabilize swale on North end as soon as possible if work is done
Stabilize	Detention Ponds	Stabilize detention ponds asap- weeds are not considered vegetation
Silt fence	Detention Pond	Reset silt fence along detention pond behind Residences
Rock	Access Rd/Const. Entrance	Need more rock at construction entrance

Have items noted on the last inspection been corrected? \square Yes \boxtimes No (if no explain): Need to stabilize in-active areas, det. ponds, and swale--Weeds do not count as vegetation. Need more rock at entrance.

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 7 days, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

Signature: (




ВМР	Location	Observation, Effectiveness, & Corrective Actions Ordered
Streets	All	Clean streets and curbs
Silt fence	Along curb	Replace silt fence where torn through along curb
Inlets	Various	Clean inlets
Inlets	End of stub street near East side	Silt built up against inlet needs removed and silt fence in front needs reset/replaced
Inlets	Residences	Inlet new inlet protection at all new inlets











Welch Silt Fence & Erosion Control, LLC