

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20253134
Address: 4400 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Wes Bears	Failed	Monday, August 11, 2025

Corrective Action Required:

1	Miscellaneous Correction	-Fire block needed every 10' along wall between stud and basement wall -Fire block all fur downs and drop ceiling -Support the soffit that spans over 4' and duct work along the ceiling
---	--------------------------	--

Comments: