

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20235681
Address: 3200 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Partial	Wednesday, September 03, 2025

Informational:

1 Misc

Elevator fire barrier:

- inner side wall screw pattern for all floors OK
- attic side OK
- outer side 3rd floor OK

Stair fire barrier:

3rd floor:

- walls and ceiling screw pattern OK

2nd floor:

1st floor:

Corrective Action Required:

2 Misc

****Protect all fire barrier gap and penetrations**

Comments: