

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20252922, Public Works Right of Way Permit Address: 211 NW CARSON DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Bob Burns Passed Thursday, September 11, 2025

Corrective Action Required

1 Misc The pipe has been sealed to the inlet. The area around the pipe

needs to be grouted.

Corrective Action Required

2 Misc The sidewalk, sod, and connection to storm box, and

infiltration trench have been installed to plan and restoration is

complete. Pass.

**Comments:**