

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**OnlinePortal at DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20235681  
Address: 3200 NE WILSHIRE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                      | Inspector:   | Outcome: | Date:                      |
|----------------------------------|--------------|----------|----------------------------|
| <b>Rated Assembly Inspection</b> | Khanh Nguyen | Partial  | Friday, September 12, 2025 |

Informational:

1 Misc

Elevator fire barrier:

- inner side wall screw pattern for all floors OK
- attic side OK
- outer side 3rd floor OK

Stair fire barrier:

3rd floor:

- walls and ceiling screw pattern OK

2nd floor:

- demising walls 1st layer

**\*\*Correction: engineer to address shear walls. Plan calls for 2 layers of GB**

1st floor:

Corrective Action Required:

2 Misc

**\*\*Protect all fire barrier gap and penetrations**

**Comments:**

