

EVERSTEAD

3741 NE TROON DR LEE'S SUMMIT, MO 64064 (816) 399 -4901

Inspector		Inspection Date Time		Time		
Bradley Huxol		10 OCT '25		1345		
Address	City	Permi	Permit # Owner/Builder			
2782 SW 11th Terrace	Lee's Summit	PRF	PRRES20254019 Summit Homes			
Inspection Type		Subdivision		Lot#		
Footing		Hig	Highland Meadows		171	
Site Conditions (all must o	comply if applicable)	Sla	b (Basement or Gara	ge As Marked	<u>d)</u>	
 ☑ Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements). ☑ Soils – bearing capacity as determined by: ☑ Bearing on undisturbed soil @ 1,500 psf ☐ Per engineer report (comment or attach report) 			Formed & Reinforced Per City Approved Dwgs Garage structural slab per approved plan Basement slab on grade per approved plan 6 mil vapor barrier installed – not required for garage slab Isolation rings or block-outs are provided over pier pads for columns			
Cold weather protection			<u>Footings</u>			
Foundation Wall Elements Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8" above proposed grading contours. Max. 12" block down at garage doors. Ufer Ground attachment rod left exposed			Reinforced per city approved plans or engineer report Deck/porch/balcony footings Footing – width, depth and location per approved plans and or engineer report Solid jumps Frost depth (min. 36 inches) Column pads – basement Column/pad at garage structural slab Ufer Ground attachment rod provided Drilled Piers (refer to footings for deck piers)			
(Give approx. location in comments)						
Retaining walls (for multip clarify which walls are bein comments) Installation per approved pla Comments: Forms and installation of re are approved for concrete.	g inspected in the ns inforcement are installed pe	er pla			(3)	
This is to certify that I, or qualified indivi-			£	STATE OF MI		

direction, inspected and/ or tested the above checked items in accordance with the applicable City approved building and site plans, codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the approved plans and specifications.

Signed: Date:

14 OCT '25

