

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**OnlinePortal at DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20235208  
Address: 2911 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	Khanh Nguyen	Failed	Thursday, November 20, 2025

Corrective Action Required:

1	CORRIDORS	-2nd and 3rd floor ceiling pre-rock OK
		4th fl-OK
		3rd fl-OK except at stair enclosures and elevator
		2nd fl: -support grid near elevator and fc above east stair enclosure door

**Comments:**