



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20254151, Public Works Right of Way Permit
Address: 2606 SW FARM FIELD RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|------------------------------|-------------|----------|---------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Site Visit Inspection | Matt Munger | Partial | Monday, November 24, 2025 |

Corrective Action Required

| | | |
|---|------|--|
| 1 | Misc | Site Visit - The service line has been installed. From the depth marks on the road they achieved adequate depth. The sidewalk was taken out and put back. They will need to restore the edges before this is closed out. |
|---|------|--|

Comments: