CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20255269

Address: 1905 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Monday, December 15,

Residential 2025

Corrective Action Required:

1 Misc -Cannot use waste stack to vent sink

-Fire block stair wall, bedroom closet and bathroom wall space from soffit

-Provide combustion air openings per code. Min 100 square inches per clear

opening. upsize 133% if grills are installed

Comments: