

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20252889
Address: 2627 SW TRACKER LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Drew Fischer	Failed	Monday, January 12, 2026

Corrective Action Required:

1	Misc	2627 SW Tracker
		- master bathroom outlet circuit hot and ground reversed
		- Front bed and bath circuit will not reset
		- Irrigation and sump outlets need label non gfci
		- Address collapsed backfill at several locations around foundation

Comments: