

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20243308
Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Sanitary Sewer - Mandrel	Patrick Schonfeldt	Partial	Wednesday, January 14, 2026

Corrective Action Required:

1	Misc	12/16/25 Tyler S. Mandrel test was was done on A line and B line. Test between Manhole A2 to A3 pass, A3 to A4 pass, A4 to A5 pass, A5 to A6 pass, A6 to A7 pass, A7 to A8 pass, A8 to A9 pass, A6 to B1 pass, B1 to B2 pass, B2 to B3 pass. Still need to test A0 to A1 and A1 to A2.
		1/14/26 PS The following sanitary line locations have passed mandrel testing: A0 to A1 and A1 to A2. Observed testing performed by Redford Construction.

Comments: