



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20260736, Public Works Right of Way Permit
Address: 2619 SW TRACKER LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Tuesday, March 03, 2026

Corrective Action Required	
1 Misc	Site visit - the line has not been installed. I will check back in a few weeks.

Comments: