

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20255276, Public Works Right of Way Permit  
Address: 220 SE GREEN ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Carrie Craver	Partial	Wednesday, April 01, 2026

Corrective Action Required

1 Misc

Work has started on 2nd at Douglas.

Corrective Action Required

2 Misc

Crew is on site working on Douglas as Maple.

Corrective Action Required

3 Misc

This work has continued north on Douglas. All pits are fenced.

Corrective Action Required

4 Misc

Pits are fenced along Douglas except at Orchard where there is active work happening.

**Comments:**