

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20120184, Building Permit - Commercial

Address: 120 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Partial Tuesday, June 12, 2012

Partial Correction

1 MISC

OK TO COVER WHEN READY GWB WALLS FULL HEIGHT @ FOLLOWING LOCATIONS: AHU RM 147 NE CORNER FOR MOUNTING OF DP-E1-28-HA; 126 & 127 FOR EQUIPMENT INSTALL; TEMPORARY EGRESS CORRIDOR @ 117; INFILL BELOW WINDOWS ALONG (DD) FROM (3.8) TO (5.1); BEHIND HVAC WALL CHASE @ 136 & 138; 119B; 119C; 120; 121; 123; 123A; 123B; 123C; 123D; 123E; 124; 125; 129; 130; 131; 132; 134; 135; BULKHEAD ABOVE DOOR 140; FOR CABLE TRAY @ PART OF CORR 143; WALL PLANE ON (7) FROM (BB.9) TO (DD); 101 FROM (A) TO (CC.3); 118; 119D; 119E; 119F;

Partial Correction 2 MISC

OK TO TOP-OUT GWB WALL DOWN TO ~ 10' A.F.F. AT FOLLOWING WALL PLANES: (CC) FROM (0.3) TO (3.7); (A.5) FROM (6.0) TO (4.9); (CC.4) FROM (0.5) TO (3.4); 149 OR-4 N WALL; 141 OR-5 N WALL; 118; ...A-CC 2-2.7 144,145 SOUTH SIDE;DD-CC 1.5-2 N7s 138; a-a.5 5.7 at door 117-2; b-cc 2.7 n side corr 143.

OK TO TOP-OUT WALL GWB DOWN TO \sim 10' A.F.F. AT FOLLOWING WALL PLANES: (CC) FROM (0.3) TO (3.7); (CC.4) FROM (0.3) TO (3.5); (A.5) FROM (6.0) TO (4.9); ON (1) FROM (B)

TO (CC);

Rated Assembly John Borns Partial Tuesday, June 12, 2012

Inspection

Partial Correction 1 MISC

OK TO COVER WHEN READY FOLLOWING COMPONENTS OF RATED ASSEMBLIES AT INTERIM CLOSURES AT ELEVATOR DOORS @ 1ST & 2ND FLOORS: FRAMING AND SHAFT LINER; 1ST + 2ND LAYERS 5/8" TYPE X GWB OK TO TAPE, MUD & FIRE-SEAL

Comments: