

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

Inspection Summary

Permit #: PRCOM20114544, Building Permit - Commercial Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	John Borns	Partial	Friday, June 29, 2012	
Partial Correction 1 MISC Partial Correction	OF F FIRE FIRE	REIGHT ELEVATOR SE CAULK; SHAFT @ 4TH	COVER WHEN READY RATED ASSEMBLY COMPONENTS EIGHT ELEVATOR SHAFT: LID COMPLETE INCLUDING AULK; SHAFT @ 4TH & 5TH FLR COMPLETE INCLUDING AULK; SHAFT @ 3RD FLR FRAMING, SHAFT LINER + TWO S 5/8" TYPE X GWB	
2 MISC	CLOSURE AT 4TH FLR S.E. CORNER PER 2/A2.8: FRAMING + SHAFT LINER + 1ST & 2ND LAYERS OF 5/8" TYPE X GWB OK TO COVER WHEN READY			
Partial Correction 3 MISC			. CORNER PER 2/A2.8: FRAMING, X GWB OK TO COVER WHEN READY	
	ASS		DY COMPONENTS OF RATED AFT: 4TH & 5TH FLOOR COMPLETE	
Partial Correction 5 MISC			0R ON (15) FROM (AA.8) TO (CC.4): ONE LAYER 5/8" TYPE X GWB; ;	
Partial Correction 6 MISC	COM		DY TYPE "A" WALL RATED ASSEMBLY DNS: SPACE 3F014 NORTH WALL N 'E X GWB;	

Rough Framing Inspection - Commercial	John Borns	Passed	Friday, June 29, 2012
In-wall Inspection	John Borns	Partial	Friday, June 29, 2012
Partial Correction 1 MISC	OK TO COVER WHEN READY BOTH FACES OF WALL FRAMING AND IN-WALL SYSTEMS AT FOLLOWING SPACES: 4F012; 4F014; 5F012; 5F014; 3F014;		

Comments: