



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20120184, Building Permit - Commercial
Address: 120 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Thursday, July 05, 2012

Partial Correction

1 MISC

OK TO COVER WHEN READY GWB WALLS FULL HEIGHT @ FOLLOWING LOCATIONS: AHU RM 147 NE CORNER FOR MOUNTING OF DP-E1-28-HA; 126 & 127 FOR EQUIPMENT INSTALL; TEMPORARY EGRESS CORRIDOR @ 117; INFILL BELOW WINDOWS ALONG (DD) FROM (3.8) TO (5.1); BEHIND HVAC WALL CHASE @ 136 & 138; 119B; 119C; 120; 121; 123; 123A; 123B; 123C; 123D; 123E; 124; 125; 129; 130; 131; 132; 134; 135; BULKHEAD ABOVE DOOR 140; FOR CABLE TRAY @ PART OF CORR 143; WALL PLANE ON (7) FROM (BB.9) TO (DD); 101 FROM (A) TO (CC.3); 118; 119; 119D; 119E; 119F; ON (DD) FROM (3.7) TO (7); 142 W WALL; ON (3) FROM (A) TO (B) CORR 143 S WALL; 136; 137; 138; 139; 140; 141; 143; 144; 145; 146; 147; 149 S,E,W WALLS; 142 ALL WALLS; MODIFICATIONS @ 136 N & 138 S; 101 SOUTH WALL; 134 PLAN EAST WALL

Partial Correction

2 MISC

OK TO TOP-OUT GWB WALL DOWN TO ~ 10' A.F.F. AT FOLLOWING WALL PLANES: (CC) FROM (0.3) TO (3.7); (A.5) FROM (6.0) TO (4.9); (CC.4) FROM (0.5) TO (3.4); 149 OR-4 N WALL; 141 OR-5 N WALL; 118; ..A-CC 2-2.7 144,145 SOUTH SIDE; DD-CC 1.5-2 N7s 138; a-a.5 5.7 at door 117-2; b-cc 2.7 n side corr 143.

OK TO TOP-OUT WALL GWB DOWN TO ~ 10' A.F.F. AT FOLLOWING WALL PLANES: (CC) FROM (0.3) TO (3.7); (CC.4) FROM (0.3) TO (3.5); (A.5) FROM (6.0) TO (4.9); ON (1) FROM (B)

TO (CC); 142;

Comments: