CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20121257, Building Permit - Commercial
Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Wednesday, January 09, 2013

Partial Correction
1   MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: 3F012; 4F017 THRU 020; 024 THRU 019; 061; 061A THRU 065; 066 thru 070; 072; 045; 075; 042; 074; 075; 076; 016; 034 THRU 041; 031; 032; 033; 016 N END; 4F020 BOTH FACES EXCEPT SE WHERE LATER TO INTERFACE W/ BLDG 100; 022 OUTSIDE FACE WHERE REMOVED FOR MODIFICATIONS AND REPLACED ; 071A; DUPLEX EMERGENCY CIRCUIT ELECT RECEPT ADDED TO HEADWALL @ IC UNITS 4F061 THROUGH 076; 071 SE; PASSENGER ELEVATOR ENTRANCES AT 2ND & 4TH FLOORS;

Rated Assembly Inspection	John Borns	Not Ready	Wednesday, January 09, 2013

Partial Correction
1   MISC

DOGLEGGED RATED WALL ASSEMBLY ABOVE CEILING @ 4F032 SOUTH END - OK TO COVER WHEN READY: FRAMING + LINER BOARD + TWO LAYERS 5/8" TYPE X GWB OK TO TAPE, MUD, AND FIRE-SEAL

Partial Correction
2   MISC

RATED CLOSURES FROM CONCRETE WALLS TO ELEVATOR DOOR FRAMES AT SURGICENTER 1ST & 2ND FLOOR OPENINGS COMPLETE

Partial Correction

3	MISC	OK TO COVER WHEN READY FOLLOWING COMPONENTS OF RATED BUMP-OUTS AT 5TH FLOOR ELEVATOR SHAFT WALLS -- ONE @ S WALL + TWO @ N WALL: FRAMING + LINER BOARD FIRE-CAULKED; TWO LAYERS 5/8" TYPE X GWB OK TO TAPE, MUD, & FIRE-SEAL

Partial Correction

4	MISC	OK TO COVER WHEN READY FOLLOWING COMPONENTS OF 5TH FLOOR RATED UTILITY SHAFT WALL: FRAMING + LINER BOARD FIRE-CAULKED; TWO LAYERS 5/8" TYPE X GWB OK TO TAPE, MUD, & FIRE-SEAL

Partial Correction

5	MISC	2ND, 3RD AND 4TH CORE BOARD AROUND ELEVATOR DOORS APPROVED 1ST LAYER.

Comments: