

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20121257, Building Permit - Commercial

Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Monday, January 28, 2013

Inspection

Partial Correction

4 MISC OK TO COVER WHEN READY FOLLOWING COMPONENTS OF

RATED WALL @ 4F021 SW: TWO LAYERS 5/8" TYPE X GWB OK

TO TAPE, MUD & FINISH

Partial Correction

5 MISC OK TO COVER WHEN READY COMPONENTS OF RATED

ASSEMBLY AT FOLLOWING LOCATIONS: S/E WALL @ 1F001 ONE LAYER 5/8" TYPE X GWB; BOTH FACES CORRIDOR CROSSWALL @ DOOR #3F007 ONE LAYER 5/8" TYPE X GWB;

In-wall Inspection John Borns Not Ready Monday, January 28, 2013

Partial Correction

1 MISC OK TO COVER WHEN READY WALL FRAMING + IN-WALL

SYSTEMS AT FOLLOWING SPACES: 3F012; 4F017 THRU 020; 024 THRU 019; 061; 061A THRU 065; 066 thru 070; 072; 045; 075; 042; 074; 075; 076; 016; 034 THRU 041; 031; 032; 033; 016 N END; 4F020 BOTH FACES EXCEPT SE WHERE LATER TO INTERFACE W/

BLDG 100; 022 OUTSIDE FACE WHERE REMOVED FOR

MODIFICATIONS AND REPLACED; 071A; DUPLEX EMERGENCY CIRCUIT ELECT RECEPT ADDED TO HEADWALL @ IC UNITS

4F061 THROUGH 076; 071 SE; PASSENGER ELEVATOR

ENTRANCES AT 2ND & 4TH FLOORS; WALL + DOOR FRAME @ 4F021 SW; 4F020 SE & SW WALLS; 4F021 NW WALL; CORRIDOR

1F001; BOTH FACES OF	CORRIDOR	CROSSWALL	@ DOOR
#3F007;			

Comments: