



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20121257, Building Permit - Commercial
Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Thursday, January 31, 2013

Partial Correction
1 MISC

OK TO COVER WHEN READY FOLLOWING COMPONENTS OF RATED WALL @ 4F021 SW: TWO LAYERS 5/8" TYPE X GWB OK TO TAPE, MUD & FINISH

Partial Correction
2 MISC

OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLY AT FOLLOWING LOCATIONS: S/E WALL @ 1F001 TWO LAYERS 5/8" TYPE X GWB; BOTH FACES CORRIDOR CROSSWALL @ DOOR #3F007; AT NEW DOOR OPENING 1F007C AT EXISTING SURGERY WAITING ROOM OK TO TAPE, MUD & FIRE-SEAL AFTER TWO LAYERS OF 5/8" TYPE X GWB ARE IN PLACE

In-wall Inspection	John Borns	Partial	Thursday, January 31, 2013
---------------------------	------------	---------	----------------------------

Partial Correction
1 MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: 3F012; 4F017 THRU 020; 024 THRU 019; 061; 061A THRU 065; 066 thru 070; 072; 045; 075; 042; 074; 075; 076; 016; 034 THRU 041; 031; 032; 033; 016 N END; 4F020 BOTH FACES EXCEPT SE WHERE LATER TO INTERFACE W/ BLDG 100; 022 OUTSIDE FACE WHERE REMOVED FOR MODIFICATIONS AND REPLACED ; 071A; DUPLEX EMERGENCY CIRCUIT ELECT RECEPT ADDED TO HEADWALL @ IC UNITS

4F061 THROUGH 076; 071 SE; PASSENGER ELEVATOR
ENTRANCES AT 2ND & 4TH FLOORS; WALL + DOOR FRAME @
4F021 SW; 4F020 SE & SW WALLS; 4F021 NW WALL; CORRIDOR
1F001; CORRIDOR CROSSWALL @ DOOR #3F007; AT NEW
DOOR OPENING 1F007C AT EXISTING SURGERY WAITING
ROOM; WALL & DOOR MODIFICATIONS AT DOOR OPENING
1A090

Comments: