

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

Inspection Summary

Permit #: PRCOM20121257, Building Permit - Commercial Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Tuesday, March 05, 2013
Partial Correction 1 MISC	SYS THR 074; BOT BLD MOE CIRC 4F02 ENT 4F02 1F00 DOC ROC 1A09 THR	TEMS AT FOLLOWING U 019; 061; 061A THRU 075; 076; 016; 034 THR H FACES EXCEPT SE G 100; 022 OUTSIDE FA DIFICATIONS AND REP CUIT ELECT RECEPT A THROUGH 076; 071 RANCES AT 2ND & 4TH 21 SW; 4F020 SE & SW 01; CORRIDOR CROSS OR OPENING 1F007C A OM; WALL & DOOR MOL 00; 1F090 W WALL FRO EE WALLS APPROVED	DY WALL FRAMING + IN-WALL SPACES: 3F012; 4F017 THRU 020; 024 065; 066 thru 070; 072; 045; 075; 042; U 041; 031; 032; 033; 016 N END; 4F020 WHERE LATER TO INTERFACE W/ ACE WHERE REMOVED FOR LACED ; 071A; DUPLEX EMERGENCY ADED TO HEADWALL @ IC UNITS SE; PASSENGER ELEVATOR 1 FLOORS; WALL + DOOR FRAME @ WALLS; 4F021 NW WALL; CORRIDOR WALL @ DOOR #3F007; AT NEW T EXISTING SURGERY WAITING DIFICATIONS AT DOOR OPENING OM B/6 TO SOUTH; ROOM 1A010 D; IN-FILL FRAMING & ELECT @ 1A090 1A090 9'Hx14'W SECTION OF W WALL;

Comments: