



CITY OF LEE'S SUMMIT  
CODES ADMINISTRATION  
220 SE GREEN ST.  
P.O.BOX 1600

PHONE:  
816-969-1200

FAX:  
816-969-1201

## Inspection Summary

---

Permit #: PRCOM20121257, Building Permit - Commercial  
Address: 110 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>In-wall Inspection</b>	John Borns	Partial	Friday, April 05, 2013

Partial Correction  
1 MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: 3F012; 4F017 THRU 020; 024 THRU 019; 061; 061A THRU 065; 066 thru 070; 072; 045; 075; 042; 074; 075; 076; 016; 034 THRU 041; 031; 032; 033; 016 N END; 4F020 BOTH FACES EXCEPT SE WHERE LATER TO INTERFACE W/ BLDG 100; 022 OUTSIDE FACE WHERE REMOVED FOR MODIFICATIONS AND REPLACED ; 071A; DUPLEX EMERGENCY CIRCUIT ELECT RECEPT ADDED TO HEADWALL @ IC UNITS 4F061 THROUGH 076; 071 SE; PASSENGER ELEVATOR ENTRANCES AT 2ND & 4TH FLOORS; WALL + DOOR FRAME @ 4F021 SW; 4F020 SE & SW WALLS; 4F021 NW WALL; CORRIDOR 1F001; CORRIDOR CROSSWALL @ DOOR #3F007; AT NEW DOOR OPENING 1F007C AT EXISTING SURGERY WAITING ROOM; WALL & DOOR MODIFICATIONS AT DOOR OPENING 1A090; 1F090 W WALL FROM B/6 TO SOUTH; ROOM 1A010 THREE WALLS APPROVED; IN-FILL FRAMING & ELECT @ 1A090 E WALL; JAN CLO 1A092; 1A090 9'Hx14'W SECTION OF W WALL; 1A090 S WALL + S 20' OF E WALL; 12' OF TYPE "P" WALL @ 1A090 W; 1F151A; 1A090 SOUTH WALL; 090C NORTH & EAST WALLS; 090B EAST WALL; REMAINDER OF AFFECTED WALLS IN 1A090 SE CORNER, 090A & 090B

**Comments:**