



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20122702, Building Permit - Commercial
Address: 308 SE DOUGLAS ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	John Borns	Partial	Monday, May 06, 2013

Partial Correction
1 MISC

SYSTEMS ABOVE BOTTOM CHORD OF ROOF/CEILING JOISTS IN 202 OK TO CONCEAL WITH INSULATION

Partial Correction
2 MISC

SOFFIT FRAMING AND ABOVE-CEILING SYSTEMS OK TO COVER WHEN READY AT **1ST FLOOR EAST ENTRANCE AND 2ND FLOOR EAST VERANDA**

In-wall Inspection	John Borns	Partial	Monday, May 06, 2013
---------------------------	------------	---------	----------------------

Partial Correction
1 MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: 106 THRU 113; 200; 201; 202; 203; 204; 206 INCLUDING N WALL; 207; 208; 201 W WALL @ STAIRWELL;

Rated Assembly Inspection	John Borns	Partial	Monday, May 06, 2013
----------------------------------	------------	---------	----------------------

Partial Correction
1 MISC

OK TO COVER WHEN READY FOLLOWING COMPONENTS OF RATED WALLS AT STAIRWELL: **201 W WALL @ STAIRWELL EAST FACE;**

Corrective Action Required
2 MISC

OK TO COVER WHEN READY FOLLOWING COMPONENTS OF
RATED WALLS AT ELEVATOR SHAFT:

Comments: