



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20130027, Building Permit - Commercial
Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086
Unit: 120, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Tuesday, June 11, 2013

Partial Correction
1 MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT: 1F126; 127; 128A; 129; 131; 132 LINAC #1; **AT VAULT DOOR @ LINAC CONTROL 1F131;**

Rough Framing Inspection - Commercial	John Borns	Partial	Tuesday, June 11, 2013
----------------------------------------------	------------	---------	------------------------

Partial Correction
1 MISC

OK TO COVER WHEN READY:

PARAPET/COPING FRAMING AT RADIOLOGY BUNKER ROOF COMPLETE.

EXTERIOR FRAMING 12 LINE TO 14 LINE AND DD LINE TO EE LINE.

RAISED FLOOR FRAMING AT DISPLAY 1F008A

Above Ceiling Inspection	John Borns	Partial	Tuesday, June 11, 2013
---------------------------------	------------	---------	------------------------

Partial Correction

1 MISC

OK TO COVER WHEN READY GWB CEILING FRAMING +
ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: SOFFITS AT
1F200; SOFFIT AT CORR 1F108 NW; SOFFIT AT 1F101; **GWB
CEILING AND PERIMETER BULKHEADS @ LINAC 1F132;**

Partial Correction

2 MISC

OK TO COVER WHEN READY ACT CEILING FRAMING +
ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: ALL PLAN
NORTH OF CORR 1F007 EXCEPT 007A, 008, 008A; 1F109; 110;
113; 114; 115; 116; 117; 138; 141; 142; 143; 144; 145;

Comments: