



# LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

### ☐ CHANGES

<b>BUSINESS NAME</b>	STANLEY EVENT CENTER		
<b>ADDRESS</b>	308 SE DOUGLAS ST, LEES SUMMIT, MO 64063		
<b>OWNER/OPERATOR NAME</b>	TXR ARCHITECTS & CONSTRUCTORS:	<b>TELEPHONE</b>	<NO PRIMARY PHONE>
<b>ADDRESS</b>	685 GRAND VIEW DR SUNRISE BEACH, MO 65079 Primary: <NO PRIMARY PHONE> Cell: (573) 434-6422		
	Steve Spencer @ 913-980-3576		

## EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

## LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-2	Map#: 195G	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20122702

## LOSS REDUCTION NARRATIVE

### ☐ NO VIOLATIONS NOTED

### ☐ ALL VIOLATIONS RESOLVED

Last Inspection      1st Inspection      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
<b>Occupancy Inspection - Fire</b>	Joe Dir	Temporary C of O	Wednesday, July 10, 2013
Corrective Action Required:			
1	(1)address the exterior of the front and rear entry doors with the numerics of 308 readable from the roadway, in a contrasting color with the background (2)label the sprinkler room access door "sprinkler room" (3)1st,2nd,3rd floor elevator smoke detectors in hallway need to be uncovered (4) smoke detector in the elevator control room needs to be uncovered (5)obtain elevator certification through state inspection (6)open j-box in elevator control room (7)secure the compressed gas bottles in the cooler room (8)3rd floor / patio exit/emerg lights missing. (9) keys for the knox box - front enrty door, 3rd floor rear entry door, security gate to rear stairs, sprinkler room door, elevator override		

<b>Alarm Test</b>	Joe Dir	Passed	Wednesday, July 03, 2013
<b>Sprinkler - Hydrostatic Test</b>	Joe Dir	Passed	Tuesday, June 18, 2013
<b>Sprinkler - Flow Test</b>	Joe Dir	Passed	Wednesday, July 03, 2013
DATE OF REPORT July 10, 2013	INSPECTOR Joe Dir	PREVENTION FOLLOW-UP REQUIRED? <input checked="" type="checkbox"/> <b>Yes</b> <input type="checkbox"/> <b>No</b>	RESPONSIBLE SIGNATURE