

Temporary Certificate of Occupancy

Permit #: PRCOM20132383
Address: 209 SE M 291 HWY, LEES SUMMIT, MO 64063
Inspected On: Tuesday, January 21, 2014
Inspected By: Mike CopelandMike CopelandMike CopelandJoe Dir
Expiration Date: 1/31/2014 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	Mike Copeland	Temporary C of O	Tuesday, January 21, 2014

Corrective Action Required:

1 MISC

- REAR NORTH DOOR WILL NO SHUT AND LATCH
- REAR SOUTH DOOR PANIC HARDWARE IS NOT WORKING PROPERLY
- SUBMIT BACKFLOW TESTS TO WATER UTILITIES

Above Ceiling Inspection	Mike Copeland	Passed	Tuesday, January 21, 2014
---------------------------------	---------------	--------	------------------------------

Occupancy Inspection - Fire Joe Dir

Temporary C of O

Tuesday, January 21,
2014