

Inspection Summary

Permit #: PRRES20131169, Building Permit - Residential

Address: 600 NW LILAC PL, Unit:B, LEES SUMMIT, MO 64081600 NW LILAC PL, Unit:C, LEES SUMMIT, MO 64081600 NW LILAC PL, Unit:A, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Piping Inspection - Residential	John Borns	Not Ready	Wednesday, January 29, 2014

Partial Correction

1 MISC

NO ISSUES FOUND ON GAS PIPING MATERIAL AND WORKMANSHIP. GAS PIPING PRESSURE TEST HELD STEADY AT ≥ 10 PSI FOR ≥ 10 MIN. AT UNIT(S): A; B;

CENTRAL METERING. GAS SERVICE RELEASE NOT REQUIRED.

Corrective Action Required

2 MISC

LSCO 7-608: GAS PIPING PRESSURE TEST BELOW LEE'S SUMMIT 10 PSI REQUIRED MINIMUM. GAUGE AT UNIT "C" READS 3.5 PSI.

Comments: