

## Inspection Summary

Permit #: PRRES20131169, Building Permit - Residential

Address: 600 NW LILAC PL, Unit:B, LEES SUMMIT, MO 64081600 NW LILAC PL, Unit:C, LEES SUMMIT, MO 64081600 NW LILAC PL, Unit:A, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Gas Piping Inspection - Residential</b>	John Borns	Partial	Thursday, January 30, 2014

Partial Correction

1 MISC

**GAS PIPING PRESSURE TEST HELD STEADY AT  $\geq 10$  PSI FOR  $\geq 10$  MIN. AT UNIT(S): A; B; C**

CENTRAL METERING. GAS SERVICE RELEASE NOT REQUIRED.

CRAWL SPACE PIPING SUBJECT TO INSPECTION WHEN ALL UNDER-FLOOR SYSTEMS ARE READY.

**Comments:**