

Certificate of Occupancy

Permit #: PRCOM20132383
Address: 209 SE M 291 HWY, LEES SUMMIT, MO 64063
Inspected On: Friday, January 31, 2014
Inspected By: Mike Copeland

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Mike Copeland Codes Commercial	Full C of O		Friday, January 31, 2014

Comments: