

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20132180, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Partial Friday, January 31, 2014

Inspection

Partial Correction

1 MISC OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING

SYSTEMS @ FOLLOWING SPACES:SOFFITS AT CORRIDORS 203 & 207 @ (16), (16.4), (18.1), (18.4); LOBBYS 200 & 204; NURSE STATION 150 SOFFITS; HARD

LID 11' AFF @ ELEV LOBBY 200; OVAL FACIA @ 9'-8";

Partial Correction

2 MISC OK TO COVER WHEN READY SHOWER LIDS AT: 031 THRU 060;

In-wall Inspection John Borns Partial Friday, January 31, 2014

Partial Correction

1 MISC OK TO TOP-OUT WALLS WITH GWB TO ALLOW INSTALLATION OF HVAC DUCT

AND OTHER SYSTEMS AT FOLLOWING LOCATIONS: CORRIDOR 5A203 FROM (13.1) TO (18.7); SPACE 140; 143; 162; CORR 5A207 FROM (19) TO (11); ON

(17) FROM (B') TO (C'); 118 BOTH FACES;

Partial Correction

2 MISC OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT

FOLLOWING SPACES: 5A115; 143; 070; 137; 139; 140; 141; 208; CORR 203 FROM (19) TO (17); PATIENT 047 THRU 059; 060 EXCEPT HEADWALL & SE PLUMBING WALLS IN BA; 061; CORR 201/202/203 COMPLETE FROM (19) TO (10.5) EXCEPT AT NURSE STATION DROPS/SOFFITS; CORRIDOR CROSSWALL @ FIRE DOOR 5A203; 016 THRU 046; RR133; RR134; 135 EXCEPT SE CORNER @ R.D. STACKS; 136; 147; 148; 149 N WALL; CORR 102 E & S WALLS FROM (8) TO (11); 060B; 203; CORR 207 W WALL (13.7) TO (19); 125 E,S,W WALLS; 153; 124; 206; 123; 121 EXCEPT SHORT WALL; 061A; 063; 062; CORR CROSS-WALL @ DOOR 102; CORR 102 W WALL FROM (8) TO (11); 037 THRU 046; 031 THRU 036; ABOVE DOOR 207; [115; 115A; 116; ABOVE DOOR 201; [CHASE WALLS @ B.5' BETWEEN (B) & (C): 151 S WALL OK TO COVER TO DECK (NOTE TYPE K);



CODES ADMINISTRATION

125 N WALL OK TO COVER TO ABOVE CEILING (NOTE TYPE L); CHASE WALL @ 121A SE; BOX CHASE @ B'.3/15; **FRAMING TO WRAP COLUMNS @ A.8/9.5 & A.8/10.5**;

Comments: