

Certificate of Occupancy

Permit #: PRRES20131167
Address: 622 NW WILLOW DR, Unit:B, LEES SUMMIT, MO 64081622 NW
WILLOW DR, Unit:C, LEES SUMMIT, MO 64081622 NW WILLOW DR, Unit:A, LEES SUMMIT, MO
64081
Inspected On: Thursday, July 10, 2014
Inspected By: John BornsJohn BornsJohn Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Plot Plan Inspection	John Borns	Passed	Thursday, July 10, 2014
Occupancy Inspection - Codes Residential	John Borns	Full C of O	Thursday, July 10, 2014
Occupancy Inspection - Codes Residential	John Borns	Full C of O	Thursday, July 10, 2014

Comments: "WELLS" FOUND IN PLACE AT GAS FEEDER ENTRIES AT UNITS "B" AND "C".